

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Butte County Public Works

Big Chico Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A

Lindo Channel Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Lindo Channel Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Department Of Water Resources

Paradise Dam

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Encroachments	A
	Erosion Areas	M

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Lake County Watershed Protection District

Clover Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
M	Culverts: Inlets / Outlets	M
	Sluice/Slide Gates	A
	Concrete Surfaces	M

Highland Canal Diversion Weir And Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Culverts: Inlets / Outlets	A

Flood Control Project Maintenance**2008 Structure Summary Report****Overall Unit and Item Ratings****Lower San Joaquin Levee District****Ash Slough Drop Structure No. 1**

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Erosion Areas	M
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Ash Slough Drop Structure No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Erosion Areas	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Ash Slough Drop Structure No. 3

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Ash Slough Drop Structure No. 4

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	M
	Revetments	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Bear Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Electric Gate Operators	A
	Concrete Surfaces	M
	Concrete Foundations	A
	Monolith Joints	A

Flood Control Project Maintenance**2008 Structure Summary Report****Overall Unit and Item Ratings****Lower San Joaquin Levee District (cont.)****Eastside Bypass Control Structure**

Overall Unit Rating	Rated Item	Item Rating
A	Encroachments	A
	Revetments	A
	Sluice/Slide Gates	A
	Electric Gate Operators	A
	Concrete Surfaces	A
	Concrete Foundations	A
	Other Metallic Items	A
	Monolith Joints	A

Eastside Bypass Drop Structure No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Eastside Bypass Drop Structure No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

Fresno River Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Encroachments	A
	Revetments	A
	Culverts: Inlets / Outlets	A
	Flap Gates	A
	Manual Operations	M
	Concrete Foundations	A

Mariposa Bypass Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Revetments	M
	Electric Gate Operators	A
	Concrete Surfaces	A
	Concrete Foundations	A
	Closure Structures	A
	Other Metallic Items	A
	Monolith Joints	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Lower San Joaquin Levee District (cont.)

Mariposa Bypass Drop Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Concrete Surfaces	A
	Concrete Foundations	A
	Monolith Joints	A

Owens Creek Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Concrete Surfaces	U
	Concrete Foundations	A
	Closure Structures	A

Owens Creek Overflow Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Revetments	M
	Culverts: Inlets / Outlets	A
	Concrete Surfaces	A
	Concrete Foundations	A

San Joaquin River And Chowchilla Canal Bypass Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A
	Sluice/Slide Gates	A
	Electric Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Monolith Joints	A

San Joaquin River Structure And Sand Slough Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Encroachments	A
	Revetments	A
	Manual Operations	A
	Concrete Surfaces	A
	Concrete Foundations	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Madera County FCWCA

Ash And Berenda Slough Control Structures

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Revetments	A
	Concrete Foundations	A
	Closure Structures	A
	Trash Rakes	M

Fresno River Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
M	Encroachments	U
	Concrete Foundations	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Merced Irrigation District

Black Rascal Creek Drop Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Encroachments	A
	Concrete Foundations	A
	Security Fencing	A

Owens Creek Siphon Structure

Overall Unit Rating	Rated Item	Item Rating
M	Culverts: Inlets / Outlets	M
	Concrete Foundations	A

Flood Control Project Maintenance

2008 Structure Summary Report

Overall Unit and Item Ratings

Plumas County

**North Fork Feather River Diversion Channel Drop Structure Drop Structures
No. 1 & 3 Through 7**

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Surfaces	A

North Fork Feather River Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Culverts: Inlets / Outlets	A
	Trash Racks	A
	Electric Gate Operators	A
	Closure Structures	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Reclamation District No. 0999

Elk Slough Inlet Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Erosion Areas	A
	Culverts: Inlets / Outlets	A
	Manual Operations	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

Sacramento Maintenance Yard

Cache Creek Setting Basin Weir And Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Revetments	A
	Sluice/Slide Gates	A
	Concrete Surfaces	A
	Security Fencing	A
	Closure Structures	A

Fremont Weir

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Revetments	A
	Concrete Surfaces	A
	Other Metallic Items	A

Knights Landing Outfall Structure

Overall Unit Rating	Rated Item	Item Rating
A	Erosion Areas	A
	Metal Pipes	A
	Flap Gates	A
	Sluice/Slide Gates	A
	Electric Gate Operators	A
	Manual Operations	A
	Concrete Surfaces	A
	Security Fencing	A
	Trash Rakes	A

Sacramento Weir

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Manual Operations	A
	Concrete Surfaces	A

Flood Control Project Maintenance
2008 Structure Summary Report
Overall Unit and Item Ratings

San Joaquin County Flood Control District

Duck Creek Diversion Weir And Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Revetments	A
	Sluice/Slide Gates	A
	Concrete Surfaces	A
	Concrete Foundations	A

Flood Control Project Maintenance

2008 Structure Summary Report

Overall Unit and Item Ratings

Sutter Maintenance Yard

Butte Slough Drainage Structure

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M

Butte Slough Outfall Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A

Colusa Weir

Overall Unit Rating	Rated Item	Item Rating
A	No Items	A

Little Chico Creek Control And Weir Structures

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Concrete Foundations	A

Moulton Weir

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Concrete Foundations	A

Nelson Bend

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Encroachments	A
	Revetments	A

Sutter Bypass Weir No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Tisdale Weir

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A

Wadsworth Canal Weir No. 4

Overall Unit Rating	Rated Item	Item Rating
A	Concrete Foundations	A